How to integrate
Dymo-M10
weighing scale with
vMeasure Parcel Ultima?

Table Of Contents

How to integrate Dymo-M10 with vMeasure Parcel Ultima?

1 – Wire Connection

Step 1: Connect the weighing scale to vMeasure Parcel Ultima.

2 – Weighing Scale Selection on the vMeasure Parcel Ultima Touchscreen

Step 2: After logging in to vMeasure Parcel Ultima, navigate to the Scale menu.

Step 3.1: Choose **Dymo-M10** from the list of weighing scales.

Step 3.2: **Default Minimum Weight:** Select the minimum weight that needs to be displayed by default when the actual weight of the product is very light.

(i) Some warehouse management systems would not consider products weighing closer to zero and this setting ensures that the minimum weight requirement is maintained.

Click **save** to finish the weighing scale integration.

The weighing scale is successfully integrated.

3 – Calibration

Step 4: Click on the **Calibration** menu.

Step 5: Select the appropriate setup height.

Step 6: Wait for 5 seconds for the system to calibrate.

Step 7: Upon successful calibration, your weighing scale will be ready for use.

vMeasure
— PARCEL ULTIMA —

Integration with **Dymo-M10**

Contact us

🌐 www.vmeasure.ai

✉️ vmeasure@visailabs.com